

From: [Wallingford, Jonni B.](#)
To: [Sheldrake, Sean](#); [Zhen, Davis](#); [Young, Hunter](#)
Cc: younghs@cdmsmith.com; [Scott Coffey](#); [Vickstrom, Kyle E.](#)
Subject: Surface water sampling
Date: Friday, November 30, 2018 12:50:52 PM
Attachments: [IMG_20181130_124300609_HDR.jpg](#)
[IMG_20181130_123043081_HDR.jpg](#)
[IMG_20181130_112744073_HDR.jpg](#)

Hello,

The Pre-RD group is currently stationed at transect 6E (RM 11.8). Once pumping began, Gravity noticed that the XAD-2 column was leaking water. Pumping was promptly stopped and the XAD column was replaced. Included is a photo of the column replacement. The Pre-RD aims to finish sampling before dark today.

Jonni

(b) (6)

XAD column exchange



Water purge



Anchoring vessel. Deploying tubing



Get [Outlook for Android](#)